# Oil Field Environmental Incident Summary

**Responsible Party:** HRC Operating, LLC **Well Operator:** HRC OPERATING, LLC

Well Name: STROMME FAMILY TRUST 157-101-11C-2-1H

Field Name: WILDCAT Well File #: 21207

Date Incident: 11/23/2014 Time Incident: 14:30 Facility ID Number:

County: WILLIAMS Twp: 157 Rng: 101 Sec: 14 Qtr: NW NE

Location Description: Stubble field SE of constructed well pad with main impacts on constructed

well pad.

Submitted By: Kelly Grimm Received By:

Contact Person: Chris Martinez

1801 California St

Suite 3500

Denver, CO 80202

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:0.3 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 2 Barrels 2 Barrels 2 barrels

**Brine** 

Other

**Description of Other Released Contaminant:** 

NA

Inspected: Written Report Received: 11/27/2015 Clean Up Concluded: 12/3/2014

Risk Evaluation:

No immediate health risk

Areal Extent:

150'x200' stubble field.

## Potential Environmental Impacts:

Off-location mpacts primarly to straw in stubble field and On-location impacts primarily to buildings/scoria

#### Action Taken or Planned:

Install cable tie to prevent accidental opening and caps on open-ended valves to prevent accidental release

Wastes Disposal Location: E&P approved disposal

Agencies Involved: NDDoH

**Updates** 

Date: 11/25/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Spray off location from a treater leak into a stubble field. Followup is necessary.

Date: 11/26/2014 Status: Inspection Author: Washek, Sandi

Updated Oil Volume: 2.00 barrels

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Arrived on site at 8:48 a.m. Weather was partly cloudy with wind out of the northwest. I walked the stubble field to the SE of the well pad and observed discoloration due to oil spray on the straw stubble. Area of impact is about 15 X 200 feet on stubble field. In addition, I observed snow discoloration along the SE side of the well pad entrance road. This area is about 50 feet long by 5 to 7 feet wide and located in the tall grass area of the pad that borders the stubble field. A company rep arrived on site and provided the name of a contact person who is in charge of the cleanup. Contacted Kelly Grimm, and she informed me the company is working with the landowner. I informed her they might want to collect the discolored snow from along the pad and grass area around the pad for proper disposal. Told the rep on site the same thing. The area surrounding the pad drains into Blacktail Dam to the south of the site. Kelly also informed the NDDoH that company is going to plug the culverts on site so nothing leaves the site. Company will provide follow-up information on the cleanup of the site.

Date: 4/27/2015 Status: Inspection Author: Washek, Sandi

Updated Oil Volume: 2.00 barrels

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

On April 24, 2015, conducted a followup inspection of the site. Weather was sunny with wind out of the SE at 10-15 mph. The field in the area of impact was plowed and being prepared for planting. No additional followup needed.